136 West Michigan Avenue (Commercial Building)
Marshall
Calhoun County
Michigan

HABS MICH, 13-MARSH,

PHOTOGRAPH

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

HISTORIC AMERICAN BUILDINGS SURVEY

136 WEST MICHIGAN AVENUE (Commercial Building)

HABS No. MI-248

Location:

136 West Michigan Avenue, Marshall, Calhoun County,

Michigan.

Significance:

A representative late 19-century small commercial building with a cast-iron store front of interesting architectural

character, partially altered.

Architectural information:

Exterior: Two-story, three-bay front, approximately 25 feet wide. Faces south.

First story: There are three bays, the central one being a recessed entrance and slightly narrower than the outer bays, which are display windows. The two outer cast-iron piers are double the width of the two inner ones; they are paneled, the panels containing ornaments at the top and bottom, and a pair of ornaments near mid-height. Each of the ornamental units contains two curled foliations (in sequence). Above each pier is a bracket, those over the double piers being double; between brackets are transom lights, divided by a wooden mullion in the center. The store windows are replacements and do not retain any divisions which the originals may have had. Above the brackets is a plain brick frieze formed by facing the iron (possibly steel) lintel. Above the frieze is a simple cornice of slight projection.

A low brickwork below the display windows and at the sides of the recessed entrance is of recent origin.

The name "Buffalo Eagle Iron Works" appears on the iron castings.

Second story: Three tall, narrow windows with low semi-elliptical heads are enriched by ornamental cast-iron hood moulds and sills; there are two ornamental corbels under each sill. The double-hung sash appear original; they have four lights over four lights, the central muntin being a colonette. The topmost lights are semi-elliptically arched and the small central spandrel is ornamented. Above the windows are the arcaded and corbeled brickwork. There was probably a cornice, which is now lost. The second-story wall is brick. There are interior shutters on the windows.

Prepared by: Harley J. McKee

Architect, Historic American

Buildings Survey September 2, 1965

Edited by:

Susan McCown

Historian, Historic American

Buildings Survey November 14, 1984